



July 20, 2007

*****AUTO**MIXED AADC 400

|||||

***** IMPORTANT SAFETY NOTICE *****

Dear Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Cummins Inc. has decided that a defect which relates to motor vehicle safety exists in recreational vehicles that contain the connecting rods of the ISL CM850 recreational vehicle engines manufactured between October 17, 2005 and April 18, 2006. We believe that your Cummins engine listed below was manufactured during that time period:

Engine Serial Number:	46600432
Vehicle Manufacturer:	FREIGHTLINER CHASSIS CORP
Vehicle Serial Number:	CX74721

The defect affects the connecting rods in ISL CM850 recreational vehicle engines. The defect could cause a piston pin joint seizure that could result in an engine failure without warning, possibly resulting in a vehicle crash.

The campaign repair involves recalibration of the engine and, to further enhance the Engine Protection System, installation of a crankcase pressure sensor, to provide early detection of the failure and avoid serious damage. This should take approximately 4 hours to complete, and will be performed free of charge. We urge you to contact your nearest Cummins authorized repair location to conduct this campaign. You may also contact the Cummins Customer Assistance Center at 1-800-DIESELS (1-800-343-7357).

If you are a lessor of vehicles with engines that are in the affected population, Federal Law requires vehicle lessors receiving this recall notice to forward a copy of this notice to the lessee within ten (10) days. You may be eligible to receive a reimbursement for the cost of obtaining a pre-notification remedy related to this recall. Please note our contact number below.

Cummins Inc.
500 Jackson Street
Columbus, IN 47201 USA
Phone 1 812 377 5000
cummins.com

If you have a complaint relative to this campaign, you may report it to the following:

Administrator, National Highway Traffic Safety Administration
400 Seventh Street, SW
Washington, DC 20590

Or, you may call the toll free Auto Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

We apologize for the inconvenience this campaign may cause. Cummins is initiating this action because of the sense of responsibility Cummins has for customer safety and customer satisfaction with our products. Thank you for your attention to this matter.

Sincerely,

A handwritten signature in black ink, appearing to read "Bryan R Rathert", with a horizontal line extending to the right from the end of the signature.

Bryan R Rathert
Executive Director – Service Engineering
Cummins Inc.